


DATE March 29, 1983

YZ250K/490K RIGHT-HAND SIDE COVER BREAKAGE

The right-hand side cover on YZ250K and YZ490K models may break under certain conditions. To make this breakage less likely, modify the inside of the side cover as shown.

Remove the material indicated by the black areas in the photo. A bench grinder may be used to remove the material. Take care to make all edges smooth.



SERVICE COPY	SER MGR	MECH	MECH	MECH	BINDER
OFFICE COPY	GEN MGR	SALES	PARTS	BINDER	PAGE 1 OF 1